




REI 60 VARIO

1



2



x 2

3



x 2
C1-09100

4




x 2
C1-09105

5




x 4
K3-06403
Ø6 x 40 TX30

6




x 4
C1-09060

7



8



45mm



9




x 8
K3-06403
Ø6 x 40 TX30

10



x 4
K3-02134
M6 x 16

11




x 1
K2-17295

12



x 3
K3-06280
Ø4 x 25

13



x 1
K2-22325

14



x 4
K3-04016
Ø6

15



x 4
R2-40145
M6

17




x 2
K3-06013
Ø4 x 20


16

Ø 28mm

800mm



x 1
K1-17299



Example 1
Exemple 1
Beispiel 1
Voorbeeld 1
Eksempel 1

A = 3040 mm


11	D	A	B	C
	°	mm	mm	mm
Pos. 1	67	3195	1652	2067
	70	3265	1492	1982
	73	3326	1329	1891
Pos. 2	67	3090	1617	1940
	70	3157	1463	1856
	73	3216	1306	1767
Pos. 3	67	2977	1583	1810
	70	3042	1436	1727
	73	3099	1285	1639

Example 2
Exemple 2
Beispiel 2
Voorbeeld 2
Eksempel 2


A = 3200 mm

11	D	A	B	C
	°	mm	mm	mm
Pos. 1	67	3195	1652	2067
	70	3265	1492	1982
	73	3326	1329	1891
Pos. 2	67	3090	1617	1940
	70	3157	1463	1856
	73	3216	1306	1767
Pos. 3	67	2977	1583	1810
	70	3042	1436	1727
	73	3099	1285	1639

Pos. 1




Pos. 2 / 3




3						
	9		10			
	Pos. 1	Pos. 2	Pos. 3	Pos. 1	Pos. 2	Pos. 3
	Pos. C	Pos. B	Pos. B	Pos. B	Pos. B	Pos. A

4

Pos. B







Pos. A / C





Pos. A


Pos. C










9






10












12






15





19



20

